





WHEEL SYSTEMS
Service Manual

Bearing
Adjustment







**FRONT HUB : 2004 – 2011 VIGOR, ÉLAN, DAUPHINÉ, VCX, 58CX TANDEM,
TT & TdF; 2004 -2007 ASPIN & ECHELON** *[refer to exploded assembly view below]*



1. Loosen the three (3) set screws by inserting a 2mm Hex wrench in the access hole in the hub shell. For 2007 and earlier models, the hub will have one (1) set screw and the access hole may be on the hub shell outboard of the flange (not shown). For 2007 and later models, the access hole will be through the outer diameter of the flange (shown).
2. Remove the adjustable side end cap from the hub. If needed, thread a M6 bolt into the adjustable side end cap and pull on the bolt for a better grip, or drive the end cap out with a drift. Once the adjustable side end cap is removed, the adjustment collar will be visible.



3. Place the wheel on a work surface with the non-adjustable side end cap facing downward. Push downward on the hub to ensure that the non-adjustable end cap is fully seated against the hub bearing. Push the adjustment collar inward, ensuring it is fully seated against its hub bearing.



4. Replace the adjustable-side end cap carefully, so as not to move the axle or adjustment collar. Hold the non-adjustable-side end cap to prevent movement.
5. Tighten the set screws. Check adjustment. If bearing play remains, repeat the above steps. This can also be performed without removing the adjustable side end cap if you are careful to push on the adjustment collar and not the adjustable side endcap.

REAR HUB 2004 – 2011 VIGOR, ÉLAN, DAUPHINE, VCX, 58CX, TANDEM, TT & TdF; 2004 -2007 ASPIN & ECHELON *[refer to exploded assembly view below]*

STEP 1.
Loosen 3 set screws
½ turn





FIGURE 10


STEP 2.
Remove Adjustable
End Cap



1. Loosen each of the three set screws ½ turn by inserting a 2mm hex wrench in the access hole in the hub shell.
2. Remove the adjustable side end cap from the hub. If needed, thread a M6 bolt into the adjustable side end cap and pull on the bolt for a better grip, or drive the end cap out with a drift. With the adjustable side end cap removed, the adjustment collar is visible.




STEP 3.
Push on Adjustment Collar and Non-Adjustable Side End Cap



3. Apply inward pressure on the non-adjustable side end cap and the adjustment collar simultaneously; making certain both parts are contacting the hub bearings. It is not necessary to maintain pressure.

STEP 4.
Replace Adjustable Side End Cap



4. Replace the adjustable-side end cap carefully, so as not to move the axle or adjustment collar. Hold the non-adjustable-side end cap to prevent movement.
5. Tighten the three set screws. If bearing play remains, repeat the above steps.

FRONT AND REAR HUBS: 2008 -2011 ASPIN AND ECHELON (INCLUDING SL MODELS), 58RSC, 38RSC; 2006 – 2007 APEX & TEMPO

These hubs have no bearing adjustment. Axle end play typically indicates worn bearings or axle. Inspect these parts and replace as needed. See the bearing replacement instructions in this manual.